



# Tech Info Library

## Personal LaserWriter NT: Minimum Margin Reduces Lines Per Page

Revised: 1/30/92  
Security: Everyone

Personal LaserWriter NT: Minimum Margin Reduces Lines Per Page

=====

Article Created: 21 January 1992  
Article Last Reviewed:  
Article Last Updated:

TOPIC -----

I have a Macintosh LC with 2MB RAM and an HD40 SC running system software version 6.0.8. I have an Apple IIe Card installed and am printing to a Personal LaserWriter NT from AppleWorks and Publish It.

When printing, the print starts an extra half-inch down the page, thereby misaligning subsequent pages -- the last page of one print job I measured had a top margin of 4 inches.

Is there a compatibility problem with the Apple IIe Card and the Personal LaserWriter NT?

DISCUSSION -----

This indicates that software is not properly configured for the correct number of lines per page. The Personal LaserWriter NT has a minimum margin that reduces the number of available lines per page to 61 from the usual 66 lines for an 8.5x11 page. Configure your software accordingly.

The Apple IIe Card version 2.0 software uses the printer driver in the Macintosh System Folder. Ensure that you have the Courier 10-point font installed.

Copyright 1992, Apple Computer, Inc.

Tech Info Library Article Number:9639