



Tech Info Library

Macintosh LC II: Why No Two-Floppy Configuration

Revised: 3/19/92
Security: Everyone

Macintosh LC II: Why No Two-Floppy Configuration

=====
Article Created: 23 March 1992
Article Last Reviewed:
Article Last Updated:

TOPIC -----

Why is a two floppy drive configuration not offered on Macintosh LC II?

DISCUSSION -----

The second floppy drive was removed to save cost and space on the logic board. In addition, the two-floppy configuration is an undesirable System 7 platform.

Copyright 1992, Apple Computer, Inc.

Tech Info Library Article Number:9956