

## Tech Info Library

## PowerBook Fax Sender 1.1.2 or Later: Fixes Page Length (7/93)

Revised: 5/16/94 Security: Everyone

PowerBook Fax Sender 1.1.2 or Later: Fixes Page Length (7/93)

\_\_\_\_\_\_

Article Created: 24 March 1992

Article Reviewed/Updated: 15 July 1993

TOPIC -----

When I send a fax from my PowerBook, the pages print out at the receiving fax machine with an extra 1/2 inch of white space at the top and bottom. The pages tear off in a non-standard size.

DISCUSSION -----

The problem you refer to is a known problem with early Fax Sender versions. Apple recommends that you upgrade to Fax Sender 1.1.2 or later to correct the problem. Fax Sender 1.1.2 is installed from the Express Modem 1.0.4 disk and is backward compatible with the PowerBook Fax/Data Modem.

Article Change History:

07/15/93 - Retitled and Updated with Fax Sender upgrade information.

Support Information Services

Copyright 1992, 1993, Apple Computer, Inc.

Tech Info Library Article Number:9988