



Tech Info Library

Quadra 950, A/UX 3.0: Serial Switch Setting for System V Spooler

Revised: 2/19/93
Security: Everyone

Quadra 950, A/UX 3.0: Serial Switch Setting for System V Spooler

=====
Article Created: 19 February 1993

TOPIC -----

It appears that Quadra 950s running A/UX 3.0 using the System V spooler (lp) and serial ports have the same problem that the IIfx had running A/UX 2.0 with System V spooler (lp) and serial ports.

DISCUSSION -----

Symptoms: Spool some jobs using lp to a serial port on a Quadra 950. Cancel a spool job. The port locks up (and sometimes the Quadra as well).

Solution: The Quadra 950 needs the Serial Switch (1.1) set to compatible mode to successfully use the System V spooler.

Copyright 1993, Apple Computer, Inc.

Tech Info Library Article Number:11606