



Tech Info Library

System 7.1: 32-Bit Enabler and Drive7 Incompatibility (3/93)

Revised: 7/27/93
Security: Everyone

System 7.1: 32-Bit Enabler and Drive7 Incompatibility (3/93)

=====
Article Created: 30 March 1993
Article Reviewed/Updated: 26 July 1993

TOPIC -----

I have been unable to start my Macintosh SE/30 with the 32-Bit System Enabler, version 1.0.3, installed. I am also using Drive7 formatting software, driver version 2.3.2. I have already tried the various suggestions of doing a clean install of System 7.1, and removing inits.

DISCUSSION -----

It has been verified that there is a third-party compatibility problem with the 32-Bit System Enabler, Version 1.0.3. The 32-Bit System Enabler is incompatible with versions 2.3.2 (and before) of Casa Blanca Works, Inc.'s Drive7 formatting software. When the 32-Bit System Enabler is used on a system which has been formatted with Drive7, the system will not start up.

Casa Blanca Works, Inc. is releasing a new version, 2.3.4, which they report corrects this problem.

To locate a vendor's address and phone number, use the vendor name as a search string.

Article Change History:
26 July 1993 - Company title updated from Casa Blanca to Casa Blanca Works, Inc.

Copyright 1993, Apple Computer, Inc

Tech Info Library Article Number:11908