



# Tech Info Library

## Super ATM 3.6: Works Fine with Macintosh AV Computers (11/93)

Revised: 11/19/93  
Security: Everyone

Super ATM 3.6: Works Fine with Macintosh AV Computers (11/93)

=====  
Article Created: 18 November 1993

TOPIC -----

I have problems using Adobe's Super ATM, version 3.5 on a Macintosh 660AV or 840AV. The scenario is as following :

- Adobe uses the Apple Installer to install SuperATM,
- at the end of the installation, you must reboot your Macintosh,
- the Macintosh reboots correctly, except that the system freezes with the clock mouse and the menu bar staying white.

Does the Hardware System Update 2.0.1 solve this problem? I've tried to install this extension after installation of Super ATM and it doesn't change anything.

DISCUSSION -----

Apple just learned that Super ATM, version 3.6 works fine with the AV computers (660AV and 840AV). Upgrade to version 3.6 and there should be no more problems.

In regard to Hardware System Update 2.0.1, that release does not actually load anything on the AV computers. You can run it, but nothing will change. It would not have fixed the problem you were experiencing.

Copyright 1993, Apple Computer, Inc.

Tech Info Library Article Number:14006