



Tech Info Library

Newton Connection Kit for Windows: -10066 Error (1/94)

Revised: 1/20/94
Security: Everyone

Newton Connection Kit for Windows: -10066 Error (1/94)

=====

Article Created: 11 January 1994

TOPIC -----

After starting a synchronization, both the Newton MessagePad and the Newton Connection Kit for Windows display error -10066.

How do I recover from this?

DISCUSSION -----

If this occurs during a synchronization with the Connection Kit for Windows, install either the 1.04 update (if you have 1.0 ROMs) or the 1.11 update (if you have 1.1 ROMs). These updates can be found on the Windows Connection Kit Disk. Their filenames are SYSUPD104.PKG (for 1.0 ROMs) and SYSUPD111.PKG (for 1.1 ROMs).

Copyright 1994, Apple Computer, Inc.

Tech Info Library Article Number:14472