



Tech Info Library

PLW 300: HyperCard Prints at Quarter Size (2/94)

Revised: 2/23/94
Security: Everyone

PLW 300: HyperCard Prints at Quarter Size (2/94)

=====
Article Created: 21 February 1994

TOPIC -----

When I print a card or stack from HyperCard version 2.1 or 2.2 to a Personal LaserWriter 300, the image is printed quarter-size (25% of normal). This problem didn't occur when I printed the same image from HyperCard to an ImageWriter and LaserWriter IINT.

What causes this?

DISCUSSION -----

This is a known bug in HyperCard (including version 2.2). It also occurs when printing from HyperCard to the Personal LaserWriter LS and LaserWriter Select 300 since all of these printers use the same printer driver.

Since each image is reduced to quarter-size, the workaround is to set the Page Setup "Reduce or Enlarge" value to 400% for full size images, 200% for half size images, and 100% for quarter size images.

Support Information Services

Copyright 1994, Apple Computer, Inc.

Tech Info Library Article Number:14614