



Tech Info Library

Power Macintosh: 6100/60 Contents Of Upgrade (3/94)

Revised: 3/29/94
Security: Everyone

Power Macintosh: 6100/60 Contents Of Upgrade (3/94)

=====
Article Created: 29 March 1994

TOPIC -----

What is contained in the M2343LL/A Power Macintosh 6100/60 Logic Board Upgrade?

DISCUSSION -----

The Power Macintosh 6100/60 upgrade contains the following items:

- HDI-45 To DB-15 Video Cable
- 50 Pin SCSI Cable
- Rear Housing Assembly, I/O bezel
- Floppy Drive Shield
- 6100 Logic Board
- Logic Board Insulator
- Power Mac 6100 Nameplate
- EMI Gasket
- Rubber Foot

- Power Macintosh 6100/60 Getting Started Manual
- Macintosh Reference Guide
- Registration Card
- A Note About Power Macintosh Logic Board Upgrade
- Additional Tips And Troubleshooting Manual
- Resource Guide 6100
- Power Macintosh CD
- Power Macintosh System Software Diskettes

Support Information Services

Copyright 1994, Apple Computer, Inc

Tech Info Library Article Number:15023