



# Tech Info Library

## Power Macintosh 6100/60AV: Contents Of Upgrade (3/94)

Revised: 3/29/94  
Security: Everyone

Power Macintosh 6100/60AV: Contents Of Upgrade (3/94)

=====  
Article Created: 29 March 1994

TOPIC -----

What is contained in the M2901LL/A Power Macintosh 6100/60AV Logic Board Upgrade?

DISCUSSION -----

The Power Macintosh 6100/60AV Logic Board Upgrade contains the following:

- HD-I45 To DB-15 Video Cable
- 50 Pin SCSI Cable
- Rear Housing Assembly, I/O bezel
- Floppy Drive Shield
- 6100 Logic Board
- Logic Board Insulator
- Power Mac 6100 Nameplate
- EMI Gasket
- Rubber Foot
  
- Power Macintosh 6100/60 Getting Started Manual
- Macintosh Reference Guide
- Registration Card
- A Note About Power Macintosh Logic Board Upgrade
- Additional Tips And Troubleshooting Manual
- Resource Guide 6100
- Power Macintosh CD
- Power Macintosh System Software Diskettes
  
- Speech Kit Instructions
- S-Video To Composite Video Input Adapter Cable
- S-Video To Composite Video Output Adapter Cable
- Plaintalk Mic
- AV Video Card
- PDS Adapter Board

Support Information Services

Copyright 1994, Apple Computer, Inc

Tech Info Library Article Number:15024