



Tech Info Library

PC Exchange: Incompatibility with Toner Tuner (4/94)

Revised: 4/28/94
Security: Everyone

PC Exchange: Incompatibility with Toner Tuner (4/94)

=====
Article Created: 28 April 1994

TOPIC -----

This article describes an incompatibility that exists when using PC Exchange with Toner Tuner 1.0 from Working Software.

DISCUSSION -----

Toner Tuner 1.0 from Working Software will cause PC Exchange to crash when a user attempts to initialize an unformatted floppy disk. This problem applies to all versions of PC Exchange. This problem has been fixed in Version 1.05 of Toner Tuner. Customers reporting this problem should contact Working Software to obtain an upgrade to Toner Tuner 1.05. To locate a vendor's address and phone number, use the vendor name as a search string.

Support Information Services

Copyright 1994, Apple Computer, Inc

Tech Info Library Article Number:15237