



Tech Info Library

LaserWriter Pro 630: Internal Termination Power Provided (5/94)

Revised: 5/5/94
Security: Everyone

LaserWriter Pro 630: Internal Termination Power Provided (5/94)

=====
Article Created: 5 May 1994

TOPIC -----

We have a LaserWriter Pro 630 with an APS internal hard drive. We are having problems printing a sample of the fonts stored on the hard drive using the LaserWriter Utility 7.6.1. What can cause this to happen?

DISCUSSION -----

It is possible that there is a termination problem. The LaserWriter Pro 630 provides internal termination power so all that is needed on the hard drive is termination; you might check with APS technologies on this. One other thing to consider is that SCSI ID's 6 and 7 are reserved, so the APS drive should be set to something different.

Support Information Services

Copyright 1994, Apple Computer, Inc

Tech Info Library Article Number:15292