



Tech Info Library

Power Macintosh: 1 MB and 2 MB SIMMs not supported (5/94)

Revised: 5/25/94
Security: Everyone

Power Macintosh: 1 MB and 2 MB SIMMs not supported (5/94)

=====

Article Created: 24 May 1994

TOPIC -----

Does the Power Macintosh support 1 MB or 2 MB 72-pin non-composite SIMMs?

DISCUSSION -----

Apple has not tested 1 MB or 2 MB SIMMS in Power Macintosh systems and therefore cannot support their use.

What this means is that there is no technical reason they should fail, however Apple cannot guarantee that you will not encounter problems in using these SIMM sizes.

Support Information Services

Copyright 1994, Apple Computer, Inc

Tech Info Library Article Number:15454