



# Tech Info Library

## Power Macintosh: Issue Using GPIB Interface Card (6/94)

Revised: 6/9/94  
Security: Everyone

Power Macintosh: Issue Using GPIB Interface Card (6/94)

=====

Article Created: 9 June 1994

TOPIC -----

I have a Power Macintosh 6100 with the NuBus adapter and I want to connect a JX-450 Professional Color Scanner from Sharp. This scanner needs to be attached to a NuBus card and it uses the NB-Handler 4.4 software. However when I use PhotoShop software I receive the error message "GPIB device 7 not found". This has been configured in the NB-Handler software.

Can you provide the NuBus slot number in the Power Macintosh 6100 when the NuBus adapter is connected? Is it possible to connect this scanner to this Power Macintosh model?

DISCUSSION -----

The NuBus slot number of the 6100 is \$E.

National Instruments (800-433-3488) in Austin, Texas is the manufacturer of the GPIB Interface for the Sharp Scanner. There is a known compatibility issue involving the use of this board with Power Macintosh systems. National Instruments has a fix for their Nubus card for Power Macintosh and can be contacted directly to upgrade the card.

Support Information Services

Copyright 1994, Apple Computer, Inc.

Tech Info Library Article Number:15575