



Tech Info Library

Power Macintosh: PowerKey May Cause Time Loss (6/94)

Revised: 6/13/94
Security: Everyone

Power Macintosh: PowerKey May Cause Time Loss (6/94)

=====

Article Created: 9 June 1994

TOPIC -----

This article describes an issue when using PowerKey from Sophisticated Circuits on Power Macintosh systems.

DISCUSSION -----

PowerKey allows users to specify when their Macintosh system turns on and off. Early versions of the control panel which is included with PowerKey may prevent the Macintosh from updating its system clock after shutdown. This will cause the internal clock to lose time.

Contact Sophisticated Circuits to obtain an update for this control panel.

Support Information Services

Copyright 1994, Apple Computer, Inc

Tech Info Library Article Number:15606