

## PowerBook 500 Series: Indicators Of A Blown Fuse (6/94)

would be heard regardless of power source, battery or AC power.

Support Information Services

Copyright 1994, Apple Computer, Inc

Tech Info Library Article Number: 15671