



# Tech Info Library

## Power Macintosh: Energy Saver Compatibility (2/95)

Revised: 2/14/95  
Security: Everyone

Power Macintosh: Energy Saver Compatibility (2/95)

=====  
Article Created: 9 August 1994  
Article Reviewed/Updated: 14 February 1995

TOPIC -----

This article describes the Energy Saver (for monitors) compatibility issue with Power Macintosh 6100/60 and 6100/60AV using the built in HDI-45 video port (AudioVision Display Port).

DISCUSSION -----

Energy Saver does not work on a Power Macintosh 6100/60 or 6100/60AV using the HDI-45 port unless one of following is installed on your Power Macintosh:

- PowerPC Enabler version 1.02
- System 7.5

Note: System Update 3.0 which included PowerPC Enabler 1.01 did not fix this problem.

Article Change History:  
14 Feb 1995 - Reviewed for technical accuracy.  
08 Sep 1994 - Clarification of wording performed.

Support Information Services

Copyright 1994-95, Apple Computer, Inc.

Tech Info Library Article Number:16010