



Tech Info Library

PowerBook: Cable Compatibility (8/96)

Revised: 8/26/96
Security: Everyone

PowerBook: Cable Compatibility (8/96)

=====

Article Created: 27 September 1994
Article Reviewed/Updated: 26 August 1996

TOPIC -----

This article provides cable compatibility information for Apple computer systems and a variety of Apple peripherals.

The left column lists the peripherals, the right column lists the cable required to connect all models of the Macintosh PowerBook computers with the exception of the PowerBook 200 and 2300 (Duo) series computers. PowerBook Duo computers may require a MiniDock or Duo Dock to utilize certain peripheral devices.

Part numbers which begin with a letter are finished goods part numbers which can be purchased from an Apple authorized reseller. The seven digit numbers are service part numbers which can only be purchased by an Apple authorized service center.

DISCUSSION -----

Begin_Table

Peripheral -----	Cable part number -----
AppleFax Modem	M0197/590-0552 (smoke)
Apple Personal Modem	
Apple Data Modem 2400	
Apple Modem 300	M0170/590-0197 & 590-0553
Apple Modem 1200	or 590-0121 & 590-0550
Apple ImageWriter II or II/L	M0197/590-0552 (smoke)
Apple ImageWriter LQ	LocalTalk optional
Apple ImageWriter Printer	590-0169 & 590-0553
Apple ImageWriter 15"	

LaserWriter, Plus,	LocalTalk, Ethernet Optional for
LaserWriter IInt, IIntx, IIif, IIg	IIg, Pro 630, Pro 810, and 16/600 PS
LaserWriter Pro 600/630/810	
LaserWriter 16/600 PS	
Personal LaserWriter NT, NTR	
Personal LaserWriter 320	
LaserWriter Select 360	

Personal LaserWriter LS	M0197/590-0552 (smoke)
Personal LaserWriter 300	
LaserWriter Select 300	
LaserWriter Select 310	
StyleWriter & StyleWriter II	
StyleWriter 1200	
Color StyleWriter/Color StyleWriter Pro	
Color StyleWriter 2400	

Any Apple (or third-party) SCSI Peripheral device	M2538LL/A (HDI-30 SCSI cable)•#&
Apple LaserWriter IIsc	
Personal LaserWriter SC	
AppleCD SC	
Apple Hard Disk 20/40/80	
Apple Tape Backup 40SC	
Apple Scanner	
Apple Color OneScanner	
Apple Color Printer	

LEGEND

- Requires M3503LL/B/658-8032 Cable Terminator in addition to the SCSI cable
- # Requires MiniDock or Duo Dock for use with PowerBook 200 and 2300 (Duo) computers
- & The M2538LL/A (HDI-30 SCSI cable) is not the same as the M2539LL/A - Apple HDI-30 SCSI Disk Adapter which enables use of the PowerBook 100 as an external hard disk with another Macintosh system.

End_Table

Article Change History:

- 26 Aug 1996 - Added begin and end table tags.
- 06 Jul 1995 - Updated ImageWriter I cable information.

Copyright 1994-96, Apple Computer, Inc

Tech Info Library Article Number:16386