



# Tech Info Library

## Power Macintosh: Generic System, Finder & Enabler Icons (5/95)

Revised: 5/18/95  
Security: Everyone

Power Macintosh: Generic System, Finder & Enabler Icons (5/95)

=====  
Article Created: 04 January 1995  
Article Reviewed/Updated: 17 May 1995

### TOPIC -----

I rebuilt my desktop and then I noticed that icons for the System, the Finder, and the PowerPC Enabler files in my new Power Macintosh 8100/110 are generic in appearance. Everything seems to work fine and rebuilding the desktop again did not resolve the problem.

What can I do to restore the proper icons?

### DISCUSSION -----

#### Problem

-----  
This is a cosmetic issue involving the system software which affects the Power Macintosh 6100/66, 7100/80, 8100/100, and 8100/110 computers. Even with the generic icons, the computers are fully functional, and the issue causes no damage to the system software.

#### Solution

-----  
Install the System 7.5 Update 1.0 to correct the issue.

These articles can help you locate the System 7.5 Update 1.0 mentioned here:

- Where To Find Apple Software Updates  
Lists online services for "free" Apple software updates.
- Obtaining Apple Product Support in the USA  
Lists 800 numbers and online services for software updates, Apple support information, and a subset of the Apple Tech. Info. Library.

Article Change History:

17 May 1995 - Added Power Macintosh 6100/66 and System 7.5 Update 1.0 info.

17 Mar 1995 - Corrected PowerPC wording.

Support Information Services

Copyright 1995, Apple Computer, Inc.

Tech Info Library Article Number:16953