

PowerBook 500 series: Global Village Modem and MacPPP (1/95)

Revised: 1/12/95 Security: Everyone PowerBook 500 series: Global Village Modem and MacPPP (1/95) ______ Article Created: 12 January 1995 I have a PowerBook 500 with a Global Village Mercury modem and am trying to use a serial protocol like MacPPP. The line drops shortly after I connect. Is there anything I can do about this? DISCUSSION -----If you have trouble maintaining a carrier using MacPPP or another PPP using a PowerPort 500, try upgrading to MacTCP 2.0.6 and try using the initialization

string AT&F%C0\N0 to turn off all compression and error correction.

Support Information Services

Copyright 1995, Apple Computer, Inc.

Tech Info Library Article Number: 17007