



Tech Info Library

PowerBook: Single Serial Port and GV Teleport II Conflict (3/95)

Revised: 3/3/95
Security: Everyone

PowerBook: Single Serial Port and GV Teleport II Conflict (3/95)

=====
Article Created: 3 March 1995

TOPIC -----

Since I installed the software for my new Global Village Teleport II modem on my PowerBook 520, I can no longer print to my StyleWriter II. What's wrong? How can I fix it?

DISCUSSION -----

The Teleport II software that ships with the new Global Village Teleport II series of modems will not allow a PowerBook with a single serial port [such as: a PowerBook 200 series (Duo), PowerBook 100, PowerBook 150 or PowerBook 500 series] to print to a serial printer while the modem driver is present in the Extensions folder within the System Folder.

The Teleport II software, if present, will constantly occupy the shared port. You will get various error messages indicating that the port is busy when you attempt to print.

The only workaround we are aware of at this time is to disable the modem software every time you want to print. You can do this by either using the an extensions or startup manager control panel device to disable the modem software or by actually removing the modem extension from the Extensions folder.

This article provides information about a non-Apple product. Apple Computer, Inc. is not responsible for its content. Please contact the vendor, Global Village, for additional information.

The Tech Info Library article titled "Locating Vendor Information" can help you search for a particular vendor's address and phone number.

Support Information Services

Copyright 1995, Apple Computer, Inc.

Tech Info Library Article Number:17305