

## Power Macintosh 9500:Incompatible w/Energy Saver Software (2/97)

Revised: 2/11/97 Security: Everyone

Power Macintosh 9500:Incompatible w/Energy Saver Software (2/97)

\_\_\_\_\_

Article Created: 10 July 1995 Article Reviewed/Updated: 11 February 1997

TOPIC -----

Why can I not get the Ecologic module in Berkley System's After Dark 3.0 to work with my Power Macintosh 9500 computer?

DISCUSSION -----

This module in After Dark relies on Apple's Energy Saver software. The Energy Saver software in System 7.5.2 is incompatible with the Power Macintosh 9500 series of computers.

Ecologic module of After Dark 3.0 is compatible with the Energy Saver software in System 7.5.3 or later. You should update your system software with system software updates which can be found at Apple Computer's online software update locations.

These articles can help you locate the software update mentioned here:

• "Where To Find Apple Software Updates" - Lists online services for free Apple software updates.

• "Obtaining Apple Product Support in the USA" - Lists 800 numbers and online services for software updates, Apple support information, and a subset of the Apple Tech Info Library.

Article Change History: 11 Feb 1997 - Added System 7.5.3 or later is compatible.

Copyright 1995-97, Apple Computer, Inc.

Tech Info Library Article Number:18125