



Tech Info Library

Pwr Mac 9500 Series: Incompatible w/ Newton Toolkit (10/95)

Revised: 10/30/95
Security: Everyone

Pwr Mac 9500 Series: Incompatible w/ Newton Toolkit (10/95)

=====
Article Created: 12 July 1995
Article Reviewed/Updated: 30 October 1995

TOPIC -----

This article discusses compatibility between the Newton Toolkit and Power Macintosh 9500 computers.

DISCUSSION -----

The Newton Toolkit v1.0.1 and v1.5.1 are not compatible with Power Macintosh 9500 computers. There is an updater available from online services and the Internet which updates the Newton Toolkit to a beta version of 1.5.2. Newton Toolkit is a Newton software development program available through Apple Programmers and Developers Association (APDA).

In addition to the update, the latest System Enabler is needed on the Power Macintosh 9500. This enabler can be found on v2.0 of the Power Macintosh 9500 compact disc. Open Transport v1.0.6 and later also installs the latest System Enabler.

SYMPTOM: Error Message - "Could Not Obtain Required Resource" when opening the Newton Toolkit Application.

SOLUTION: Updated Power Macintosh 9500 Enabler and Newton Toolkit.

SYMPTOM: Newton Toolkit Application crashes without an error.

SOLUTION: Updated Power Macintosh 9500 Enabler and Newton Toolkit.

Article Change History:

30 Oct 1995 - Added information on obtaining new version of Toolkit.

Support Information Services

Copyright 1995, Apple Computer, Inc.

Tech Info Library Article Number:18143