



Tech Info Library

Power Mac 5200, 5300, & 6200: Software Updates Read Me (11/95)

Revised: 3/20/96
Security: Everyone

Power Mac 5200, 5300, & 6200: Software Updates Read Me (11/95)

=====

Article Created: 22 November 1995

TOPIC -----

This article provides information about the software updates on the system software CD for the Power Macintosh 5200/75 LC, 5300/100 LC, and the 6200/75 LC series computers.

DISCUSSION -----

About the Macintosh Software Updates

This document provides important information about some system files installed on your computer.

When you are finished reading and printing this document, choose Quit from the File menu to quit the SimpleText application program.

The following system extensions and control panel have been installed on your computer's hard disk:

- At Ease 7.5 Layer Patch: if you have At Ease installed on your machine this extension fixes a potential problem when trying to launch an application or selecting the menu item "Go To Finder" with At Ease. This is only a problem if you have desktop hiding enabled in the General Controls control panel.
- Processor Info Extension: fixes a potential problem that could cause your computer to report back the incorrect processor and bus speeds.
- Audio Volume Extension: if you have an internal modem installed (not related to Express modem), this extension fixes a problem where no sound is emitted by the modem. This extension also fixes a potential problem where poor sound quality may be heard.
- Screen Control Panel: fixes a problem that could cause your computer to behave

incorrectly when Screen Power Saver mode is enabled.

If you reinstall system software, you should also reinstall these files. To reinstall, drag each file into your System folder. Click OK when you are asked whether to put each file in their respective folders.

Support Information Services

Copyright 1995, Apple Computer, Inc.

Tech Info Library Article Number:18969