



Tech Info Library

Power Macintosh 7500 & 8500: Vertical Lines Follow Cursor (1/96)

Revised: 3/21/96
Security: Everyone

Power Macintosh 7500 & 8500: Vertical Lines Follow Cursor (1/96)

=====

Article Created: 10 January 1996

TOPIC -----

I have a Power Macintosh 7500 series computer, and I have recently noticed that two vertical lines appear to be following the cursor. What could cause this, and how can I resolve it?

DISCUSSION -----

Improper installation of VRAM on Power Macintosh 7500 and 8500 series computers causes these symptoms. If you have 2 MB of VRAM installed, you must install the VRAM DIMMs into the slots labeled 1. For example:

- 1 _____ 1 MB VRAM DIMM
- 2 _____
- 1 _____ 1 MB VRAM DIMM
- 2 _____

Also, you cannot install 3 MB of VRAM. The Power Macintosh 7500 and 8500 series computer allow only for 2 and 4 MB VRAM configurations.

Support Information Services

Copyright 1996, Apple Computer, Inc.

Tech Info Library Article Number:19204