

Power Macintosh 9500: Using a Epson Stylus Color Printer (2/96)

Revised: 2/8/96 Security: Everyone Power Macintosh 9500: Using a Epson Stylus Color Printer (2/96) ______ Article Created: 8 February 1996 TOPIC -----This article describes how to resolve printing issues when printing from a Power Macintosh 9500 to an Epson Stylus Color printer. DISCUSSION -----In order to successfully print from a Power Macintosh 9500 series computer to an Epson Stylus Color printer, follow these steps. Step 1 ____ Use the latest Epson printer driver. The drivers are posted on CompuServe, on Epson's BBS, and on Epson's web page: http://www.epson.com According to Epson, you can use version 2.0.3AE for serial connections and use version 2.0.2 for LocalTalk connections. Note that there are several versions of the Epson Stylus Color printer, and each has a slightly different driver. Contact Epson to verify which driver is recommended for your printer. Step 2 ____ Upgrade the firmware on the printer's motherboard. Contact Epson to identify the ROM size and upgrade it to the proper version. Step 3 ____ Upgrade to Open Transport v1.0.8, which is available on the online services. Step 4 ____ Install the System 7.5.2 Printing Fix 1.1, which is also available on the online

..TIL19317-Power_Macintosh_9500-Using_a_Epson_Stylus_Color_Printer_2-96_(TA35059).pdf

services.

This article provides information about a non-Apple product. Apple Computer, Inc. is not responsible for its content. Please contact the vendor for additional information.

The Tech Info Library article titled "Locating Vendor Information" can help you search for a particular vendor's address and phone number.

These articles can help you locate the software update mentioned here:

• "Where To Find Apple Software Updates" - Lists online services for free Apple software updates.

• "Obtaining Apple Product Support in the USA" - Lists 800 numbers and online services for software updates, Apple support information, and a subset of the Apple Tech Info Library.

Support Information Services

Copyright 1996, Apple Computer, Inc.

Tech Info Library Article Number:19317