

DOS Compatible Card: Open Transport or Classic Network (6/96)

Revised: 6/21/96 Security: Everyone

DOS Compatible Card: Open Transport or Classic Network (6/96)

Article Created: 28 March 1996 Article Reviewed/Updated: 21 June 1996

TOPIC -----

After installing the System 7.5 Update 2.0, I am unable to do networking from the DOS side of my Power Macintosh 6100 DOS Compatible. I have also tried this on an LC 630 DOS Compatible and a Performa 640 DOS Compatible. None of these are able to do networking with Open Transport, but they work properly with Classic networking.

DISCUSSION -----

Apple has released version 1.5 of the DOS Compatibility software and strongly recommends that all owners of previous version of DOS Compatibility cards (except the Macintosh Centris/Quadra 610 DOS Compatibility Card), upgrade to this version of software. This software requires an upgrade to Mac OS 7.5.3 with System 7.5 Update 2.0. With the Power Macintosh 6100, Macintosh LC 630, and Macintosh Performa 640 DOS Compatibility cards, Classic networking must be chosen instead of Open Transport.

- If you have a PCI-based computer, you need DOS Compatibility software 1.5, System 7.5.3, and use Open Transport 1.1. Version 1.5 of the DOS Compatibility Software ships with the PC Compatibility Cards.
- If you have a Non-PCI-based computer (for example, a Power Macintosh 6100 DOS Compatible, LC 630 DOS Compatible, or Performa 640 DOS Compatible), you need DOS Compatibility software 1.5, System 7.5.3, and use Classic networking by selecting this option in the Network Software Selector found in the Apple Extras folder.

Article Change History: 21 Jun 1996 - Complete rewrite of article. 12 Jun 1996 - Added supported computers. ..TIL19524-DOS_Compatible_Card-Open_Transport_or_Classic_Network_6-96_(TA35238).pdf

Copyright 1996, Apple Computer, Inc.

Tech Info Library Article Number:19524