



Tech Info Library

Power Macintosh 5400/120: Need to Install Revision 2? (7/96)

Revised: 7/13/96
Security: Everyone

Power Macintosh 5400/120: Need to Install Revision 2? (7/96)

=====
Article Created: 14 June 1996
Article Reviewed/Updated: 13 July 1996

TOPIC -----

I have seen the list of computers that should have System 7.5.3 Revision 2 installed on them. However, I have a Power Macintosh 5400/120 computer, which I thought had Revision 2 pre-installed on it, but this computer is not among those listed. Do I need Revision 2 on this computer? If so, why is it not listed with the others?

DISCUSSION -----

The Power Macintosh 5400/120 requires System 7.5.3 Revision 2. However, Revision 2 is already pre-installed on the hard drive and included in the system software installer on the CD-ROM disc. Since Revision 2 is already installed, you do not need to re-install it using the updater installer. The list of computers that should have Revision 2 installed includes only those computers that need to be updated. It does not include computers that ship with Revision 2 already installed.

This article was published in the Information Alley on 14 June 1996.

Article Change History:
13 Jul 1996 - Added alley info.

Copyright 1996, Apple Computer, Inc.

Tech Info Library Article Number:20039