



# Tech Info Library

## Network Assistant: Talk - Requires Dual Channel Sound (8/96)

Revised: 8/22/96  
Security: Everyone

Network Assistant: Talk - Requires Dual Channel Sound (8/96)

=====  
Article Created: 12 July 1996  
Article Reviewed/Updated: 22 August 1996

TOPIC -----

Will the "Talk" feature in the Network Assistant work with all Macintosh computers?

DISCUSSION -----

The "Talk" feature in the Apple Network Administrator Toolkit requires a Macintosh with dual channel sound capabilities. In other words, a computer that can record and playthrough sound at the same time.

The "Talk" feature will not work with the systems listed below :

- Macintosh Classic
- Macintosh Classic II
- Macintosh Color Classic
- Macintosh Color Classic II
- Macintosh SE/30
- Macintosh IIfx
- Macintosh IIfx
- Macintosh IIfx
- Macintosh LC
- Macintosh LC II
- Macintosh LC III
- Macintosh LC 475
- Macintosh LC 520
- Macintosh LC 550
- Macintosh LC 575
- Macintosh Quadra 605

- Macintosh Performa 200
- Macintosh Performa 250
- Macintosh Performa 275

Macintosh Performa 400  
Macintosh Performa 405  
Macintosh Performa 410  
Macintosh Performa 430  
Macintosh Performa 450  
Macintosh Performa 460 Series  
Macintosh Performa 475  
Macintosh Performa 476  
Macintosh Performa 520  
Macintosh Performa 550  
Macintosh Performa 560  
Macintosh Performa 570 Series  
Macintosh Performa 600 Series

Macintosh PowerBook Duo 200 Series  
Macintosh PowerBook Duo 2300\*  
Macintosh Duo MiniDock  
Macintosh Duo Dock  
Macintosh Duo Dock II  
PowerBook Duo Dock Plus

\* Although the Macintosh PowerBook Duo 2300 is able to record and playthrough sound simultaneously, the Talk feature is disabled on this system due to a software issue discovered late in the process.

Article Change History:

22 Aug 1996 - Added two Macintosh computers to list.

Copyright 1996, Apple Computer, Inc.

Tech Info Library Article Number:20163