

## PowerBook 1400: SoftWindows 95 Cannot Read CDs (11/95)

Revised: 11/14/96 Security: Everyone

PowerBook 1400: SoftWindows 95 Cannot Read CDs (11/95)

\_\_\_\_\_\_

Article Created: 14 November 1996

TOPIC -----

I have installed Insignia Solutions SoftWindows '95 on a PowerBook 1400 series computer. Everything seems to function as expected when I am working in SoftWindows '95 except that it does not recognize anything in the CD-ROM drive in the Windows environment.

DISCUSSION -----

SoftWindows '95 needs to be upgraded to version 1.0.2 or later in order to recognize ATAPI interface CD-ROM drives (like the CD-ROM drive in the PowerBook 1400 series computers). A patch to version 1.0.2 can be found on the Insignia Solutions' ftp site: ftp.insignia.com.

This article provides information about a non-Apple product. Apple Computer, Inc. is not responsible for its content. Please contact the vendor, Insignia, for additional information.

The Tech Info Library article titled "Locating Vendor Information" can help you search for a particular vendor's address and phone number.

This article was published in the Information Alley on 14 November 1996.

Copyright 1996, Apple Computer, Inc.

Tech Info Library Article Number: 20637