



Tech Info Library

Pwr Mac 6360/Performa 6400: Pulse Dialing Does Not Work (3/97)

Revised: 3/3/97
Security: Everyone

Pwr Mac 6360/Performa 6400: Pulse Dialing Does Not Work (3/97)

=====
Article Created: 31 January 1997
Article Reviewed/Updated: 3 March 1997

TOPIC -----

I cannot use pulse dialing to fax from the Apple Telecom software. It always defaults to tone dialing.

DISCUSSION -----

Apple is aware of the issue. However, at this time there are no known workarounds, and there is no date estimates when this will be corrected in the Telecom software.

Article Change History:
03 Mar 1997 - Added current information.

Copyright 1997, Apple Computer, Inc.

Tech Info Library Article Number:20909