



Tech Info Library

PowerBook 3400 & Open Transport 1.1.2 Incompatibility (3/97)

Revised: 4/21/97
Security: Everyone

PowerBook 3400 & Open Transport 1.1.2 Incompatibility (3/97)

=====
Article Created: 12 March 1997

TOPIC -----

I installed Open Transport (OT) 1.1.2 on my PowerBook 3400 computer. All seemed well until the computer went into sleep mode and then it froze. I have been able to reproduce this several times. What is wrong?

DISCUSSION -----

There are some incompatibilities between Open Transport 1.1.2 and the PowerBook 3400 computer. We were able to reproduce freezing by repeatedly switching between IRTalk and Printer/Modem port in the AppleTalk control panel.

We suggest you reinstall Open Transport 1.1.1. There are no fixes in Open Transport 1.1.2 that apply to the PowerBook 3400 computer.

Copyright 1997, Apple Computer, Inc.

Tech Info Library Article Number:21113