

Apple Service - Troubleshoot and Repair

[Home](#) - [CD Index](#) - [Feedback](#)

Tech Info Library

[Apple Spec DB](#) - [Hard Drives Matrix](#) - [Memory Guide](#) -
[Parts DB](#) - [Service Manuals](#) - [Software Troubleshooting](#)

[Service Programs Manual Index - U.S.](#) - [Canada](#)

[CompTIA Codes](#) - [Ordering Parts FAQ](#) - [Product Service
Matrix](#) - [REAs](#) - [Service Excellence](#)

TITLE

PowerBook G3 Series (Bronze Keyboard): Mold Lines in
Plastic

Article ID: 31053
Created: 7/16/99
Modified: 12/21/99

TOPIC

*** RESTRICTED: Apple Internal and Support Providers Only *
Not For General Public Release**

The PowerBook G3 Series (Bronze keyboard) has mold lines in the plastic. Is this normal?

DISCUSSION

Mold lines will appear during the manufacturing process. On the PowerBook G3 Series (Bronze keyboard), these lines are faintly visible on the top case between the keyboard and trackpad, and between the trackpad and trackpad button.

These mold lines are normal, and the unit does not need to be repaired.

EXTENDED Information - [Apple Internal Use - Service Providers and Support Professional](#)

Document Information

Product Area: Computers

Category: PowerBook

Sub Category: PowerBook G3 Series (Bronze Kbd)

APPLE NEED-TO-KNOW CONFIDENTIAL: Do NOT forward, copy, or otherwise replicate or disseminate verbally, electronically, or in hardcopy (except to those individuals within your organization who have a legitimate business need to know the information, and who have agreed in writing, to keep it confidential), unless Apple has given prior written authorization.

Copyright © 1999-2000, Apple Computer, Inc.