

[Home](#) - [CD Index](#) - [Feedback](#)

Tech Info Library

[Apple Spec DB](#) - [Hard Drives Matrix](#) - [Memory Guide](#) -
[Parts DB](#) - [Service Manuals](#) - [Software Troubleshooting](#)

[Service Programs Manual Index - U.S.](#) - [Canada](#)

[CompTIA Codes](#) - [Ordering Parts FAQ](#) - [Product Service
Matrix](#) - [REAs](#) - [Service Excellence](#)

TITLE

PowerBook G3 Series (Bronze keyboard): Heatsink
Reinstallation Tip

Article ID: 58405
Created: 6/10/99
Modified: 6/10/99

TOPIC

This article provides an important tip when reinstalling the processor heatsink in the PowerBook G3 Series (Bronze keyboard).

DISCUSSION

When reinstalling the heatsink, for example after a memory upgrade, be sure that the ferrite bead on the display cable is not under the heatsink. If the ferrite bead is under the heatsink, the EMI gasket and ferrite bead will stack up possibly causing a slight bow in the keyboard after reinstallation.

Before screwing the heatsink down, gently push the ferrite bead towards the rear of the PowerBook creating the necessary clearance for the heatsink.

EXTENDED Information - [Apple Internal Use - Service Providers and Support Professional](#)

Document Information

Product Area: Computers
Category: PowerBook
Sub Category: PowerBook G3 Series (Bronze Kbd)

APPLE NEED-TO-KNOW CONFIDENTIAL: Do NOT forward, copy, or otherwise replicate or disseminate verbally, electronically, or in hardcopy (except to those individuals within your organization who have a legitimate business need to know the information, and who have agreed in writing, to keep it confidential), unless Apple has given prior written authorization.
Copyright © 1999-2000, Apple Computer, Inc.