



# Tech Info Library

## Apple Iic External Drive : PR#7 Can't Boot

Revised: 11/10/88  
Security: Everyone

Apple Iic External Drive : PR#7 Can't Boot

=====

Article Created: 23 January 1986  
Article Last Reviewed: 17 July 1992  
Article Last Updated:

PROBLEM DESCRIPTION: Attempt to boot external disk drive PR#7.  
No boot action and the words "AppleTalk Offline" appear at the  
bottom of the screen.

CAUSE: You may have a logic board which has ROMs compatible with the  
UniDisk 3.5 installed. Using PR#7 to boot the external drive is a feature  
which was discontinued in these ROMs to make room for other new  
features.

CURE: If you are using a UniDisk 3.5 use PR#5 instead of PR#7. If  
you are using any other drive, you can not boot from the external  
drive.

Copyright 1988 Apple Computer, Inc.

Tech Info Library Article Number:1679