



Tech Info Library

Apple IIe : Double Characters Displayed in 80 Column Mode

Revised: 1/17/92
Security: Everyone

Apple IIe : Double Characters Displayed in 80 Column Mode

=====
Article Created: 22 April 1986
Article Last Reviewed: 17 July 1992
Article Last Updated: 17 July 1992

PROBLEM DESCRIPTION: Apple IIe exhibits double characters in 80 column mode.

CAUSE: Possible bad HAL chip.

CURE: Remove and replace the logic board (HAL not replaceable part) chip and test system.

If the above cure doesn't fix the problem, search on GTS and Apple IIe to obtain a general troubleshooting procedure.

Copyright 1988, Apple Computer, Inc.

Tech Info Library Article Number:1837