



# Tech Info Library

## Apple IIGS: How To Avoid Lock-up When Using Mixed Drives

Revised: 12/5/88  
Security: Everyone

Apple IIGS: How To Avoid Lock-up When Using Mixed Drives

=====

This article last reviewed: 16 November 1988

If you have an Apple IIGS systems with mixed-drive configurations (3.5" and 5.25"), you may find that when saving data under AppleWorks on the 3.5" drive, both drive lights come on and the system locks up.

The Daisy Chain controller board in your 3.5" drive probably needs to be replaced by an Apple dealer.

(NOTE: The 3.5" drive must be connected to the SmartPort, and the 5.25" drive must be plugged into the 3.5" drive.)

Copyright 1988 Apple Computer, Inc.

Tech Info Library Article Number:3451