



Tech Info Library

A/UX: VT102 Man Page Error

Revised: 1/26/93
Security: Everyone

A/UX: VT102 Man Page Error

=====
Article Created: 25 January 1993

TOPIC -----

This article corrects an error in the man page for VT102 terminal tool. The error is in the man page, both on-line and in the A/UX 3.0 Programmer's Reference, Section 7, VT102, page 14.

DISCUSSION -----

Near the end (long man page) it states: When sending Escape-Left square bracket-lower case C, (esc[c]), that the VT102 tool should respond with:

Escape-Right bracket-?6c, (esc]?6c)

The wrong bracket type is specified.

The correct sequence is:

Escape-Left bracket-?6c (esc[?6c)

Copyright 1993, Apple Computer, Inc.

Tech Info Library Article Number:11319