

Programmer's Aid #1: Problems with the memory test

Revised: 11/30/84 Security: Everyone

Programmer's Aid #1: Problems with the memory test

The memory test in the Programmer's Aid #1 diskette has a problem. According to the listing on page 86 of the manual, \$D670 contains 20 8A D6 when the ROM contains 4C CB 02. This causes the program to jump to \$02CB where there normally isn't any program. To patch around this problem, enter these instructions in the monitor before testing any memory:

02CB:20 8A D6 4C 73 D6

Apple Tech Notes

Tech Info Library Article Number:602