



Tech Info Library

AppleShare 1.0, 1.1: Incompatible with AST-4000 3.0

Revised: 10/4/89
Security: Everyone

AppleShare 1.0, 1.1: Incompatible with AST-4000 3.0

=====

This article last reviewed: 12 October 1987

Version 3.0 of the AST-4000 utilities is incompatible with AppleShare and can cause server crashes. AST Utilities version 3.2 fixes the problem. Among other things, it supports changing the SCSI address of the AST-4000. You can use AST's product BBS (714-660-9175) to download the software and send queries to the AST's Tech Support group.

Copyright 1989 Apple Computer, Inc.

Tech Info Library Article Number:864