

Tech Info Library

Macintosh Continuously Reboots Itself

Revised: 1/17/92 Security: Everyone

Macintosh Continuously Reboots Itself

Article Created: 22 April 1986

Article Last Reviewed: 17 July 1992

Article Last Updated:

PROBLEM DESCRIPTION: After being powered on the Macintosh

continuously reboots of its own initiative. During this process, it

beeps about twice a second.

CAUSE: The power supply may be defective.

IMPORTANT: To avoid damage to Macintosh modules follow the instructions exactly as given in the "CURE:" below.

CURE: 1. Replace the power supply.

- 2. Turn on the Macintosh and make all Level I adjustments.
- 3. Run MacTest. If the problem remains, replace the Main Logic PCB.
- 4. If the problem remains after step 3, replace the drive.

If the above cure doesn't fix the problem, search on GTS and the product's name to obtain a general troubleshooting procedure.

Copyright 1988, Apple Computer, Inc.

Tech Info Library Article Number: 1899