



Tech Info Library

ImageWriter II: IBM 3287 printer emulation

Revised: 8/3/89
Security: Everyone

ImageWriter II: IBM 3287 printer emulation

=====
This article last reviewed: 4 June 1986

ImageWriter II's make good replacements for the IBM 3287 dot matrix printers commonly used with the IBM 3270 family of terminal devices. The IBM 3278 terminals can be replaced with an AppleLine-Macintosh-MacTerminal combination, and you can replace the IBM 3287 printers with this simple and cost effective configuration:

Equipment	Vendor	Number
IRMAprint	DCA *	PC3287-S
ImageWriter II Printer	Apple	A9M0310
Apple II Printer 8 cable	Apple	A9C0313

--> Installation Diagram

IBM 3274/6 --> Coax cable --> IRMAprint --> Printer 8 cable --> ImageWriter II

This solution proves to be a good value because it provides better print quality and speed than the IBM 3287 or similar printers such as Telex.

* DCA is a registered trademark of Digital Communications Association, Inc.

Copyright 1989 Apple Computer, Inc.

Tech Info Library Article Number:1993