



Tech Info Library

ImageWriter LQ: Spacing Problem In Best Mode Caused By Driver

Revised: 11/6/91
Security: Everyone

ImageWriter LQ: Spacing Problem In "Best" Mode Caused By Driver

=====
Article Created: 13 February 1988
Article Last Reviewed: 6 November 1991
Article Last Updated: 6 November 1991

TOPIC -----

This article describes spacing problems with the earlier version of the ImageWriter LQ print driver, version 1.x.

DISCUSSION -----

In the box with the ImageWriter LQ is a sheet titled "ImageWriter LQ Important Information." It says: "Macintosh users: Words printed in Best Mode may occasionally touch or overlap, depending on the font, font size, or font style you use. To correct any spacing problems, try adding one or more spaces between words that are too close together."

The problem is not with the ImageWriter LQ itself, but with the ImageWriter LQ driver.

The solution is to upgrade to the ImageWriter LQ 2.0 driver.

Copyright 1988, 1991 Apple Computer, Inc.

Tech Info Library Article Number:2527