



Tech Info Library

ProDOS Can't Handle Disk Volumes Larger Than 32MB

Revised: 2/13/88
Security: Everyone

ProDOS Can't Handle Disk Volumes Larger Than 32MB

=====

This article last reviewed: 5 February 1988

Current versions of ProDOS can't handle more than 32MB of storage on a hard disk volume.

If you connect a Hard Disk 40SC or Hard Disk 80SC to an Apple II, you must partition the hard disk -- that is, divide it into separate volumes. Each volume is then counted as one SCSI device.

Apple does not supply the software that does the partitioning and currently does not know of any other source for such software.

Tech Info Library Article Number:2530