



Tech Info Library

Macintosh II: DIP- And Surface-Mounted SIMMs Are Equivalent

Revised: 7/21/92
Security: Everyone

Macintosh II: DIP- And Surface-Mounted SIMMs Are Equivalent

=====
Article Created: 10 November 1988
Article Last Reviewed: 21 July 1992
Article Last Updated:

TOPIC -----

Can both DIP-mounted and surface-mounted SIMMs be used together in a Macintosh II with HD40 SC and 4MB RAM? Are all Macintosh II computers with HD40 SC and 4MB RAM supplied with DIP-mounted SIMMs?

DISCUSSION -----

There is no problem mixing DIP-mounted and regular surface-mounted SIMMs in the same computer. To the computer, they are the same. Macintosh II computers with HD40 SC and 4MB RAM may be supplied with either DIP-mounted SIMMs or surface-mount SIMMs.

Copyright 1988 Apple Computer, Inc.

Tech Info Library Article Number:3448