



# Tech Info Library

## Mac IICI: EtherTalk & Apple Internet Router Problem (11/94)

Revised: 11/29/94  
Security: Everyone

Mac IICI: EtherTalk & Apple Internet Router Problem (11/94)

=====  
Article Created: 10 January 1991

TOPIC -----

Macintosh IICI systems running the AppleTalk Internet Router and EtherTalk have been found to "freeze up" in certain high-traffic situations. What can I do?

DISCUSSION -----

The solution is to install EtherTalk on the Macintosh IICI using the Network Products Installer that was released with System 6.0.7. This installs a new version of the .ENET driver in the System file that resolves the problem.

Copyright 1991-94, Apple Computer, Inc.

Tech Info Library Article Number:6623