



Tech Info Library

Apple Scanner: 8-Pin Port Is Non-Functional

Revised: 3/26/91
Security: Everyone

Apple Scanner: 8-Pin Port Is Non-Functional

=====
Article Created: 14 February 1991
Article Last Reviewed:
Article Last Updated:

TOPIC -----

I need information regarding the 8-Pin port that is next to SCSI port on the Apple Scanner. What is it for? (The icon indicates LocalTalk.) How can developers find out more about implementing it?

DISCUSSION -----

The port was originally intended to allow the scanner to be connected to the network. This capability was eventually dropped, so the port is essentially connected to nothing. There is no way for developers to use the port.

Copyright 1991 Apple Computer, Inc.

Tech Info Library Article Number:6776