

Apple IIGS: Remove AppleTalk Before Internal Test

Revised: 7/25/91 Security: Everyone

Apple IIGS: Remove AppleTalk Before Internal Test

Article Created: 1 May 1991 Article Last Reviewed: Article Last Updated:

TOPIC -----

I performed an internal test on my Apple IIGS using the Command-Control-Option-Reset key sequence. Soon after I did this, other computers were disconnected from the network. Did my Apple IIGS internal test cause the problem?

DISCUSSION -----

Yes. When performing an internal test on an Apple IIGS that is on an AppleShare network, be sure to disconnect the network connector. Failure to do so will cause severe communication problems with other nodes, and will usually result in other computers becoming electronically disconnected from the network.

Copyright 1991, Apple Computer, Inc.

Tech Info Library Article Number:7444