



# Tech Info Library

## PATHWORKS 1.0: No Official Support for HP LaserJet

Revised: 9/24/91  
Security: Everyone

PATHWORKS 1.0: No Official Support for HP LaserJet

=====  
Article Created: 13 August 1991  
Article Last Reviewed:  
Article Last Updated:

TOPIC -----

Does PATHWORKS 1.0 support HP LaserJet? Does the print driver from the PATHWORKS (either 6.0 or 7.0) support LaserJet?

DISCUSSION -----

Officially, PATHWORKS 1.0 Print Services only support following PostScript printers:

Printer ----- Connected to the VAX computer through -----

Digital LPS20	Ethernet
Digital LPS40	Ethernet
Digital LPS40 Plus	Ethernet
Digital LN03R	Serial Connection

Apple printers: LocalTalk/Ethernet bridge or an RS-232 serial connection

LaserWriter Plus  
LaserWriter IINT  
LaserWriter IINTX

The PATHWORKS print drivers are for the above PostScript printers only.

If you need more specific information or you have enhancement requests, contact Digital Technical Support directly.

For more information, search under: "Digital"

Copyright 1991 Apple Computer, Inc.

Tech Info Library Article Number:8608