



Tech Info Library

Apple II High-Speed SCSI Card: Using with GS (11/96)

Revised: 11/21/96
Security: Everyone

Apple II High-Speed SCSI Card: Using with GS (11/96)

=====
Article Created: 13 August 1991
Article Reviewed/Updated: 15 November 1996

TOPIC -----

I have an Apple IIGS with a High-Speed SCSI Card but am unable to access my SCSI Hard Drive. I am using the drivers that came on the System Tools disk 5.0.2.

DISCUSSION -----

You need to install the drivers on System Tools disk 5.0.4, which should support the High Speed SCSI card. The SCSI card is also self-terminating and any external terminators should be removed.

Article Change History
15 Nov 1996 - Reviewed for technical accuracy, revised formatting.

Copyright 1991-96, Apple Computer, Inc.

Tech Info Library Article Number:8762